

# **Yancey Fuel Solutions Tank Audit**

15▼7

Inspection Number

**CATERPILLAR** 

Serial Number

Model 3512

**Equipment Family ENGINE - GENERATOR SET** 

Asset ID

Make

SMU 46.2 Hours

Coordinates

Technician

**Customer Name** 

Customer Email

Work Order

Completed On

Inspector

PDF Generated On

Location



EA20437

3/22/2023 9:54:39 AM

Timothy Vickerman

3/22/2023



NORMAL

#### **General Info & Comments**

**General info/Comments** 

Comments: All systems test good at this time, no repairs recommended.









#### **Fuel Tank Information**

1.1 Fuel Tank Serial Number

WRITE YOUR ANSWER BELOW

Comments:



1.2 List associated generator(s) or equipment supplied by tank

WRITE YOUR ANSWER BELOW

Comments: Cat 3512 s/n



1.3 Fuel Tank Type

WRITE YOUR ANSWER BELOW

1.3.1 Fuel Tank Capacity

1,3,2 Tank Construction Material

6,000 Gallons steel Material

Serial Number: Asset ID:

## Comments: Remote fill port, overfill alarm



## **Fuel Tank Condition**

## 2.1 Fill Cap Condition


NORMAL



## 2.2 Tank Vents Clear?

YES (PASSED)

## Comments: 6" emergency



2.2.1 Vent Pipe Size

2 inches

2.3 Fuel Level Gauge Condition

**NORMAL** 



2.4 Spill Prevention Valve

N/A

2.5 Physical Tank Condition (Rust, Holding water on surface, Structural issues?)

NORMAL




2.6 Other Tank Notes or Comments

N/A

2.7 Fuel Level at Time of Audit

81 - 85%

Comments: 83%, fuel level acceptable





3366.6	71.5	4805.3	90.5
3406.3	72	4840	91
3446	72.5	4874.4	91.5
3485.6	73	4908.6	92
3525.2	73.5	4942.6	92.5
3564.7	74	4976.2	93
3604.1	74.5	5009.6	93.5
3643.5	75	5042.8	94
3682.8	75.5	5075.6	94.5
3722	76	5108.2	95
3761.1	76.5	5140.4	95.5
3800.2	77	5172.4	96

## **Fuel Condition**

3.1 Fuel Lab Analysis?


YES

#### Comments: Bottom



3.3 Tank Camera Scope Analysis Performed?

YES



3.4 Sediment found during camera analysis?

NO

Comments: Minor normal whispy sediment, worn fuel residue

3.5 Water found during camera analysis?

NO

3.6 Microbes found during camera analysis?

NO

3.7 Sludge found during camera analysis?

NO

3.8 Rust found during camera analysis?

NO

3.9 Fuel Inhibitor added?

YES



3.9.1 Inhibitor quantity

3.10 Biocide Required?

3.10.1 Biocided added?

3.11 Overall Fuel Condition Notes & Comments

Comments: All systems test good at this time.